



**Nickel City Line Railroad  
MANIFEST & SWITCH LIST - Page 1  
Morning Industrial Local**

<b>Lead Engine/Consist#</b>	<b>Train: Train 501T</b>
-----------------------------	------------------------------

<b>Departs: 01:01</b>	<b>Origin: Nickel City Yard</b>
---------------------------	-------------------------------------

Arrive Nickel City Yard

Nickel City Yard PICKUP:

*Block for Nickel City East-Alleghany News*

C&O	400450	Boxcar Loaded	Track 11
-----	--------	---------------	----------

*Block for Nickel City East-Artic Freeze Cold Storage*

IC	16470	ReefMech Loaded	Track 11
----	-------	-----------------	----------

*Block for Nickel City East-Barraza Lawn Guy Land*

PRR	61042	Boxcar Empty	Locomotive Yard
-----	-------	--------------	-----------------

*Block for Nickel City East-Boyce Trucking & Transfer*

COP	7309	Boxcar Empty	Track 11
-----	------	--------------	----------

*Block for Nickel City East-Kandl Oil Company*

HTCX	1710	Tank Oil Loaded	Track 11
------	------	-----------------	----------

**Hazardous**

*Block for Nickel City East-NC Power & Light Supply*

WM	2412	Flatcar Loaded	Track 11
----	------	----------------	----------

*Block for Nickel City East-NC Transfer*

NCL	860302	Boxcar Empty	Track 11
-----	--------	--------------	----------

Depart Nickel City Yard WB, 447 tons, 400 feet, 7 cars

Arrive Sheppardsfield

Uncouple from Consist and run around. Reattach to tail end of consist. ",black

Obtain Track Authority for NCE,black

No work at Sheppardsfield

Arrive Nickel City East

**OBTAIN TRACK AUTHORITY TO WORK / DEPART NCE,black**

Pull Empty Coal from NC Power. Assist Train 402 & 403 with switching prior to departing NCE,black

Nickel City East SETOUT:

C&O	400450	Boxcar Loaded	Alleghany News
-----	--------	---------------	----------------

IC	16470	ReefMech Loaded	Artic Freeze Cold Storage
----	-------	-----------------	---------------------------

PRR	61042	Boxcar Empty	Barraza Lawn Guy Land
-----	-------	--------------	-----------------------

COP	7309	Boxcar Empty	Boyce Trucking & Transfer
-----	------	--------------	---------------------------

HTCX	1710	Tank Oil Loaded	Kandl Oil Company
------	------	-----------------	-------------------

**Hazardous**

WM	2412	Flatcar Loaded	NC Power & Light Supply
----	------	----------------	-------------------------

NCL	860302	Boxcar Empty	NC Transfer
-----	--------	--------------	-------------

Obtain Track Authority to depart for SP,black

RN	CAR INFO	TRACK	X
<b>Nickel City East PICKUP:</b>			
<i>Block for Nickel City Yard-Track 10</i>			
ERIE	81426 Reefer Loaded	AlleghanyBrew	
<i>Block for Nickel City Yard-Track 16</i>			
C&O	486000 Boxcar Loaded	Foote Factory Shoes	
PRR	27294 Boxcar Empty	Mountain Tire Company	
<i>Block for Nickel City Yard-Track 8</i>			
NAFX	53133 FlatBulkHead Empty	NC Lumber	
<i>Block for Nickel City Yard-Track 9</i>			
FGCX	11516 ReefMech Loaded	AlleghanyBrew	
Depart Nickel City East WB, 366 tons, 314 feet, 5 cars			
Arrive Sheppardsfield			
Uncouple from Consist and run around. Reattach to tail end of consist. ",black			
Contact Dipatcher for clearance to enter NC Yard.,black			
No work at Sheppardsfield			
Arrive Nickel City Yard			
Detach from Consist. Turn locomotive over to Hostler.,black			
<b>Nickel City Yard SETOUT:</b>			
ERIE	81426 Reefer Loaded	Track 10	
C&O	486000 Boxcar Loaded	Track 16	
PRR	27294 Boxcar Empty	Track 16	
NAFX	53133 FlatBulkHead Empty	Track 8	
FGCX	11516 ReefMech Loaded	Track 9	
Train Terminates Nickel City Yard			
Created 2/3/2024 9:49:18 AMMC Ver			

Hold Here