

## Nickel City Line Railroad MANIFEST & SWITCH LIST - Page 1 Harrisburg Coal Run

Lead Engine/Consist#	Train:			
	Train X404			
Departs:	Origin:			
03:30	Dubois (PA)			
Arrive Dubois				
Dubois Coal Processing Plant PICKUPS:				
Block for Rochester				
10 Loaded Clean Coal Hoppe	Harrisburg			
Depart Dubois EB, 896 tons, 908 feet, 10 cars				
Arrive Waterloo Junction				
Waterloo Junction SETOUTS:				
10 Loaded Clean Coal Hoppe	Harrisburg			
Train Terminates Waterloo Junction				

				Ц	
-					
				П	
				$\vdash$	
	⊢—			Н	
ı				Ш	
1					
1					
				_	
-		<u> </u>		-	
1				Ц	
				_ ]	
				П	
				П	
۱				П	
l	$\vdash$			4	
ł				_	
l					
i					
10	1			П	
Fold Here				П	
lere				П	
				H	
1				Н	
				Н	
				Ш	
				П	
				П	
				П	
	<b></b>			H	
				Н	
				Н	
				Ш	
				Ш	
	L			LĪ	
				П	
				П	
				П	
				H	
	<u> </u>			Н	
				Н	
				Ш	
				П	
				П	
				П	
				H	
	l .			1	