

Nickel City Line Railroad MANIFEST & SWITCH LIST - Page 1 Morning Industrial Local

Lead Engine/Consist#		Train:
	•	Train 501T
	Departs:	Origin:
	01:01	Nickel City Yard
Arrive I	Nickel City Yard	
Place T	ransfer Caboose at End of T	rain,black
Nickel	City Yard PICKUP:	
	Block for Nickel City East-	Alleghany Brew-Grain
WM	602437 HopGrain Loaded	Track 11
	Block for Nickel City East-A	lleghanyBrew-Warehse
FGCX	11609 ReefMech Empty	Overflow Track
	Block for Nickel City Eas	t-Kandl Oil Company

GATX 9876 Tank Oil Loaded Hazardous

HTCX 1710 Tank Oil Loaded Track 11

Hazardous

Block for Nickel City East-NCE Short Term Storage

SDRX 8175 Tank Oil Loaded

Overflow Track

Overflow Track

Hazardous

Depart Nickel City Yard WB, 382 tons, 277 feet, 5 cars

Arrive Sheppardsfield

Obtain Track Authority for NCE.",blac

Push back to NCE (Caboose First),black

No work at Sheppardsfield

Arrive Nickel City East

OBTAIN TRACK AUTHORITY TO WORK / DEPART NCE, black

AM Only: Pull Empty Coal from NC Power. Place on Coal Siding. Assist Train 402 & 403 with switching if needed prior to departing NCE.,black

Nickel	City	East	SET	OU.	T:
--------	------	-------------	-----	-----	----

WM	602437 HopGrain Loaded	Alleghany Brew
FGCX	11609 ReefMech Empty	AlleghanyBrew
GATX	9876 Tank Oil Loaded	Kandl Oil Company
Hazard	ous	
HTCX	1710 Tank Oil Loaded	Kandl Oil Company

Hazardous

SDRX 8175 Tank Oil Loaded NCE Short Term Storage

Hazardous

Place Transfer Caboose at End of Train,black

Nickel City East PICKUP:

Block for Nickel City Yard-Track 8

WM NC Power & Light Supply 2412 Flatcar Empty

Block for Nickel City Yard-Track 11-(501,521)

RN	CAR INFO	TRACK			
FGCX	11516 ReefMech Loaded	AlleghanyBrew			
Block for Nickel City Yard-Track 13					
FGCX	11498 Reefer Loaded	AlleghanyBrew			
Block for Nickel City Yard-Track 14					
PC&O	96400 Boxcar Empty	Barraza Lawn Guy Land			
	Block for Nickel City Yard-Track 15				
NCL	860324 Boxcar Loaded	Alleghany News			
Block for Nickel City Yard-Overflow Track					
NAFX	53133 FlatBulkHead Empty	NC Lumber			
Depart Nickel City East WB, 390 tons, 358 feet, 6 cars					

Arrive Sheppardsfield

Hold on track at Sheppardsfield.,black

Contact Dipatcher for clearance to enter NC Yard. Push back (Caboose First) to NC Yard., black

No work at Sheppardsfield

Arrive Nickel City Yard

Detach from Consist. Turn locomotive over to Hostler., black

Nickel City Yard SETOUT:

WM	2412 Flatcar Empty	Track 8	
FGCX	11516 ReefMech Loaded	Track 11	
FGCX	11498 Reefer Loaded	Track 13	
PC&O	96400 Boxcar Empty	Track 14	
NCL	860324 Boxcar Loaded	Track 15	
NAFX	53133 FlatBulkHead Empty	Overflow Track	
	•		

Train Terminates Nickel City Yard

Created 5/16/2025 5:22:02 PMMC Ver